

1 If no fault has been found during previous tests (54–505 to 54–525), install new control unit as a tryout.

