

1 If no faults were found during previous tests according to job numbers 54–505 to 525, install new control unit (2) on trial.

